
50 Watt Power Supply Installation Manual (V 3.0)



- 1. **IMPORTANT!** Disconnect the power.
- 2. **IMPORTANT!** We have included two sets of cables. One set is for Surface-Mount master clocks and one is for Rack-Mount master clocks. You only need to use the set of cables that applies to your model master clock.
- 3. Connect the red female connector to the male 2-pin connector as indicated in the drawing below. Also, be sure the polarity is correct as shown in the drawing.
- 4. There are two orange connectors on the master clock relay board in the upper right corner. One of these connectors does not have any wires attached. Remove that connector and attach the orange 3-pin female connector from the additional power supply.



ORANGE 3 PIN FEMALE CONECTOR (110V)

Page 1